



Figure 1. Weight change during the oxidation of steel and copper in 40%O₂ /Ar at 500 °C.



(a)



(b)

Figure 2. Copper (a) and steel (b) after oxidation in air at 700 °C.




Figure 3. Weight change of copper and steel during oxidation in air at 500 °C under thermal cycle.




Figure 4. Copper wire after oxidation in air at 700 °C.




Figure 5. CaO-SiO₂-B₂O₃ phase diagram.



(a)



(b)

Figure 6. (a) steel rod wound copper wire and (b) steel rod after dissolution of copper oxide.




FIGURE 7




FIGURE 8